

Menu

HISTORY FILE MAP for year 2008

REAL TIME

PLAYBACK


RECALLED REALTIME

RECALLED PLAYBACK

059.03:58-07:06 3hr 08mins of playback 128 bps telemetry intermittent due to low SNR caused by ranging at DSS-14.

059.13:59-15:13 1hr 15mins of realtime 1024 bps INT telemetry intermittent due to low SNR caused by ranging at DSS-14.

060.13:10-17:03 3hr 53mins of realtime 1024 bps INT telemetry intermittent due to low SNR at DSS-14.



063.09:15-09:40 0hrs 25mins of recorded 128 bps telemetry lost due to 1-way to 2-way outage at DSS-14 during playback.

063.20:15-20:54 0hrs 39mins of recorded 128 bps telemetry lost due to 1-way to 2-way outage at DSS-63 during playback.

069.00:09-02:01 1hrs 52mins of telemetry lost or intermittent due low SNR at DSS-63 and following 1-way to 2-way outage during playback. DR M104710 refers.

066.12:57-15:21 2hrs 24mins of realtime interleaved 1024 bps telemetry intermittent due to subreflector problem at DSS-14. DR G108401 refers.